

XEROX

January 15, 1985

Ms. Sheri Bianchin Environmental Engineer U. S. Environmental Protection Agency 230 South Dearborn Street (5AC-26) Chicago, Illinois 60604

Dear Ms. Bianchin:

This is in response to your telephone call today. Enclosed is the Safety Data Sheet for product Formula 0-88 used at our Oakbrook facility.

If you need further information, do not hesitate to call.

Very truly yours,

B. Kelly Masters

Kelly Mas

Environmental Engineer

BKM:njm encl

	.*	
-		

U.S. DEPARTMENT OF LABOR Oc pational Safety and Health Administr

Form Approved OMB No. 44-R1387

Required under USDL Safety and Health Regulations for Ship Repairing

Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)							
		SECT	ION I				
MANUFACTURER'S NAME SELIG CHEMICAL INDUSTRIES	EMERGENCY TELEPHONE NO. (404) 691-9220						
ADDRESS (Number, Street, City, State, and ZIP Code)							
CHEMICAL NAME AND SYNONYMS	840 SFLIG DR SW ATLANTA, GA 30378 CHEMICAL NAME AND SYNONYMS FURMULA 0-88						
CHEMICAL FAMILY			FORMULA				
SECTION	1! -	r	RDOUSINGREDIENTS	**************************************	·		
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COA	TINGS	%	TLV (Units)	
PIGMENTS			BASE METAL				
CATALYST			ALLOYS				
VEHICLE			METALLIC COATINGS				
SOLVENTS .			FILLER METAL PLUS COATING OR CORE FLUX	-			
ADDITIVES			OTHERS				
OTHERS							
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES * TLV (Units)							
d-limonene and isomers				92	-98	NA	
Nonionic emulsifiers					8	NA	
		77.00				14/7	
					-		
	TIOI	V III - F	HYSICAL DATA				
BOILING POINT (°F.)	17	76 ⁰ C			.87		
VAPOR PRESSURE (mm Hg.)	PERCENT, VOLATILE BY VOLUME (%)		*		,		
VAPOR DENSITY (AIR=1)		EVAPORATION RATE (=1)			,		
SOLUBILITY IN WATER	en	nulsifi	es				
APPEARANCE AND ODOR Clear, light yellow color, citrus odor.							
SECTION IV -	FIR	E AND E	XPLOSION HAZARD DATA				
FLASH POINT (Method used) 118 F (TCC	}		FLAMMABLE LIMITS	Lel	Ţ	Uel	
EXTINGUISHING MEDIA							
SPECIAL FIRE FIGHTING PROCEDURES							
None.							
UNUSUAL FIRE AND EXPLOSION HAZARDS							

None

	SE	ע איי גט	• HEAI	LTH HAZARD DATA	
HRESHOLD LIMIT VI			NA		
Tritation of contact.	posure to eyes on co	intact.	Possib	le dermatitis after prolonged or frequent	
EMERGENCY AND FIF For eyes, for persists.	est AID PROCEDUR Lush with wat	er for	15 minu	tes. See a physician if irritation	
				*·	
		25251		CACTIVITY DATA	
SECTION VI - REACTIVITY DATA STABILITY CONDITIONS TO AVOID					
STABILITY	UNSTABLE		ייסון וטאט:	IS TO AVOID	
INCOMPATABILITY (A	STABLE	_xx			
HAZARDOUS DECOM					
HAZARDOO3 DECOM.			one	CONDITIONS TO AVOID	
HAZARDOUS POLYMERIZATION	MAY OCCUR	·	v		
	WILL NOT O	CCUR	X		
	SECTI	ON VII -	SPILL	OR LEAK PROCEDURES	
STEPS TO BE TAKEN	IN CASE MATERIA	L IS RELEA	ASED OR S	SPILLED	
		М	ор ир и	vith water.	
WASTE DISPOSAL ME	THOD .	. A	ny		
				•	
				PROTECTION INFORMATION	
RESPIRATORY PROT	ECTION (Specify TY)		loż requ	Wied.	
VENTILATION	Good ventile mechanical (Go	ation is	all t	nat is required.	
PROTECTIVE GLOVE	s Rubber			eve projection Avoid direct eye contact.	
OTHER PROTECTIVE	EQUIPMENT	Λ	lone		
			·		
PRECAUTIONS TO BE				CIAL PRECAUTIONS	
			•	en fire or flame.	
OTHER PRECAUTION			· ·		
		4	lone		